Rosemary Im. Red Wing Cabin (Bldg. No. 330) Olympic National Park Barnes Point, Lake Creacent Port Angeles Vicinity Clallam County Washington HABS No. WA-185-H

HARS WASH 5-POANN, QH-

## PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE INTA

Historic American Building Survey National Park Service Western Region Department of the Interior San Francisco, California 94107


## NATIONAL PARK SERVICE Department of the Interior

Gretchen A. Luxenberg, National Park Service

## HISTORIC AMERICAN BUILDING SURVEY ARCHITECTURAL DATA FORM

July, 1988

STATE	COUNTY	TOWN OR VICINITY		
	CLOLLEM		proximately 20 miles southwest of ort Angeles	
WASHINGTON HISTORIC NAME OF STRUC	CLALLAM TURE (include source f	والمستقد المستقد واستفيد في المستقد ال	HABS NO.	
	Red Wing" Cabin	······.,	WA-185-H	
SECONDARY OR COMMON				
Bldg. No. 380		•		
COMPLETE ADDRESS (for r Barnes Point, south sho from Port Angeles, in O	re of Lake Crescent,	north side of Hwy	101, approximately 20 miles	
DATE OF CONSTRUCTION (	include source)	ARCHITECT(S) (inclu	de source)	
Mid-to-late 1920s (Historic Building Inventory)		Builder and Craftsman: John Daum (HRS, 1983)		
SIGNIFICANCE (architectura		original use of struct	ure)	
This cabin was construc contributes to the over possesses integrity of association.	all character of the	rustic, picturesqu		
STYLE (if appropriate)				
Craftsman-style cottage				
MATERIAL OF CONSTRUCT	ON (include structural	systems)		
Wood-frame construction	set on 6 x 6 posts	on concrete piers.		
SHAPE AND DIMENSIONS O	F STRUCTURE (sketche	d floor plans on separ	rate sheet acceptable)	
Irregular: overall dime	nsions approx. 24' x	23'	t	
ends; wood shingle sidi "stick style" wood and	gable roof with exte ng with vertical boa stucco detailing; hi shingle rail; two e r and fascia hoards.	rd and batten above p-roofed entrance p ntry doors; diamond	aces and exposed rafter; gable ends have simple orch on west supported by pane casement sash with	
Painted floor boards; b in each sleeping room.	evelled board siding	; vertical board wa	inscotting on walls; sinks	
MAJOR ALTERATIONS AND	ADDITIONS, WITH DATE	ES		
Bathroom set on concret	e pad (later additio	n date unknown)		
PRESENT CONDITION AND	JSE	- · · · · · · · · · · · · · · · · · · ·		
Fair; Vacant				
OTHER INFORMATION AS A	PPROPRIATE	····		
"Red Wing" is the only	cabin that appears t	o be a duplex.		
SOURCES OF INFORMATION Historic Structure Repo Historic Resource Study Historic Building Inven	rt, 1986 , 1983	ional Register, State R National Re	<b>egisters, etc.)</b> gister Listing, 1979	
OMPILER, AFFILIATION TOATE		DATE		



Red Wing Building #380